





Ensure new audio unit settings allow for full range audio signal (not sub only) from RCA out connector